



**STORM DRAIN SYSTEM 001  
STRUCTURE SUMMARY AND CONDITION ASSESSMENT - 2020**

Storm Structure Number	Survey Point Number	Storm System Number	Structure Type					Condition Rating	Comments
			SDMH	CBMH	CB	OUTFALL	FIELD INLET		
101	5736	1				1		1	System outfall host pipe corroded away; riprap movement has deformed liner material; invert mostly blocked causing siltation
102	5669	1	1					3	Structure has many cracks in base; 4 of the 7 inverts abandoned; soil migration as surface deformation; deterioration of grade ring
103	5665	1		1				3	CBMH was cleaned in 2019; both pipe inverts have no grout and gravel is exposed with possible migration; infiltration at base; fractured grade ring gravel exposed; nth pipe 50% capacity
104	5670	1			1			3	CB has damaged grade rings with possible gravel migration; pipe penetration not grouted gravel exposed
105	5667	1	1					3	SDMH has sewer lid not storm; infiltration in base at grout; both north pipes abandoned; sump filled with sediment (silt)
106	5668	1		1				3	CBMH is non-standard style; sump filled with sediment; Sth pipe has severe sag with no capacity
107	5674	1		1				4	CBMH is non-standard style; had design for side access (swale); missing grout; lid was buried with gravel; pipes 50% capacity
108	5740	1		1				3	CBMH is non-standard style; lower south invert unknown length or if it ties into structure; north pipe may have crown failure
109	5692	1					1	4	Field inlet with sediment present in flow line; gravel swale upstream
110	5644	1	1					2	SDMH cone damaged, danger of collapse; base has significant sediment build up; east CMP heavily corroded with shear closer to 111
111	5642	1		1				2	CBMH has significant sediment build up in sump; east 36" CMP has severe pipe shear, pipe corrosion; west 36" CPEP has pipe joint separations
112	5643	1			1			3	CB missing grout at pipe penetration; pipe shows signs of poor compaction as it is crushed as it exits structure.
113	5641	1						3	SDMH has significant sediment build up extending into all pipes included perf; grout failure; east 36" has some shear at exit
114	5640	1	1					4	SDMH has minor grout failure; sump has sediment
115	5647	1	1					4	SDMH has grout failure; sump has sediment; both north and south pipe have significant sedimentation
116	5659	1			1			4	SDMH / CB, structure is at the end of a perf line, but has a solid lid, uncertain if surface drains to structure; sediment in sump
117	5588	1	1					4	SDMH has grout failure; sump has sediment; south pipe has severe shear causing sedimentation upstream
118	5605	1	1					4	SDMH has sediment in base
119	5585	1	1					4	SDMH has sediment in base; east invert abandoned, but still discharges ground water; full plug is approx. 15' east of invert
120	5584	1	1					4	SDMH has sediment in base; east invert has severe shear
121	5583	1					1	3	Field Inlet / CB is nonstandard with slotted casting over a 18" CPEP 90 elbow; severe shear at structure 120; gravel in flow line
122	5093	1					1	3	Field Inlet is partially blocked by gravel; pipe has gravel in flow line
123	5596	1	1					4	SDMH has minor infiltration at joint between base and cone; south pipe has full obstruction approx. 25' upstream
124	5578	1			1			4	CB has minor grout cracking; north pipe has full obstruction approx. 250' downstream
125	5591	1	1					4	SDMH east of rail tracks; base has circumferential cracking; infiltration
126	5082	1					1	4	Field Inlet east of rail tracks; inlet is partially blocked by organic material
127	5593	1	1					4	SDMH east of rail tracks; sump is full of sediment
128	5607	1	1					3	SDMH east of rail tracks; does not have access; sump full of sediment; storm pipes are surcharged
129	5075	1					1	5	Field Inlet east of rail tracks No access for maintenance
130	5590	1	1					5	SDMH east of rail tracks; does not have maintenance access
131	5582	1	1					5	SDMH east of rail tracks; does not have maintenance access
132	5096	1					1	5	Field Inlet east of rail tracks; No access for maintenance
133	5581	1	1					4	SDMH east of rail tracks; No access for maintenance
134	5579	1	1					4	SDMH east of rail tracks; does not have access; north storm pipe has severe sag fully surcharged
135	5112	1					1	3	Field Inlet east of rail tracks; inlet has gravel blocking invert
136	5576	1	1					4	SDMH east of rail tracks; No access for maintenance
137	5575	1	1					5	SDMH east of rail tracks; does not have access
138	5115	1					1	5	Field Inlet east of rail tracks; No access for maintenance
139	5619	1	1					4	No Comment
<b>Totals</b>			<b>19</b>	<b>5</b>	<b>4</b>	<b>1</b>	<b>8</b>		

Abbreviations: SDMH = Storm Drain Manhole; CBMH = Catch Basin Manhole; CB = Catch Basin; FI = Field Inlet; CMP = Corrugated Metal Pipe; DIP = Ductile Iron Pipe; CPEP = Corrugated Polyethylene Pipe; OGS = Oil & Grit Separator; PVC = Polyvinyl Chloride; CMU = Concrete Masonry Unit; CIP = Cast-In-Place

Notes: 1. Structure totals encompass all of Storm Drain System 001; which includes structures outside project limits.  
2. Pictures and Videos from the 2020 Structure and Pipe Condition Assessment can be found at: <https://aro36587742.sharepoint.com/:f/s/Files/Share/Ep-xDJOqqDBLvisRgpMsmUoBv7Wau5oMjn4ssiYyuSak0w7e=JfH8ZA>

Condition Rating Criteria:		
1	Critical	Very advanced deterioration, Replacement / Rehabilitation recommended, Safety issues are present if no action is taken, Infrastructure failure will result adjacent to structure if failure occurs
2	Serious	Advanced deterioration present, Schedule maintenance ASAP, Safety issues may be present
3	Poor	Deterioration / Damage present, Scheduled maintenance is needed, No safety issues present
4	Fair	No Defects or Damage present, No safety issues present, Structure requires maintenance
5	Good	No Defects or Damage present, No safety issues present, Maintain as normal
Indicates a specific storm structure or pipe that requires maintenance and could be a future safety concern.		



**STORM DRAIN SYSTEM 001  
PIPE SUMMARY AND CONDITION ASSESSMENT - 2020**

Storm Structure Start	Storm Structure End	Storm System Number	Pipe Size (Inch)	Pipe Type & Length (Feet)						Condition Rating	Comments
				CPEP	CPEP (SUBDRAIN)	CMP	HDPE	DIP	CIPP		
101	102	1	36						424		Host CMP pipe completely corroded at outfall
102	103	1	18	30							
102	105	1	36						69	4	Nothing in notes about this pipe, appears to be in good condition in video
103	104	1	18	207							
103	105	1	36						69		
105	106	1	12				45			3	Looking South: Second and third sections of pipe are heaved; 2/10' channelized sediment in pipe; sixth section of pipe begins to drop down; Looking North: HDPE pipe, half full channelized sediment, infiltration at 1st and 2nd joints, sag in roof at 5th joint
105	110	1	36						101	3	Looking East: a lot of sediment on both sides up to 45 degrees; Looking West: possible deformation, 1.5' channelized sediment sloped up walls
106	107	1	18			329				3	Looking South: Over 1/2 full of sediment, at 4' pipe angles down and is completely full of sediment; Looking North: Severe sag with no capacity, over half-full of sediment; infiltration present on roof and joint btwn 2nd and 3rd section looking north; deflects down
107	108	1	18			407				3	Looking South: 1/2 full of sediment, infiltration present at 1st joint, invert rusted out; Looking North: infiltration at first 5 joints
108	unk-south	1	12			50				3	Looking South: Pipe is half filled with water; cannot confirm end of pipe
108	109	1	18			90				3	Looking South: Ovaling at beginning, 4th section bulging on Eastside, 0.1' gravel in pipe; Looking North: joint btwn. 2nd and 3rd section is disconnected, slight deflection after third section
110	111	1	36			356				2	Severe pipe shear / joint separation; soil migration; Looking East: infiltration present btwn. 2nd and 3rd sections of pipe, separation/shear btwn. 3rd and 4th sections of pipe, 4th section drops down
111	112	1	18		362					3	Looking North: tear present after structure; Looking South: pipe drop exiting structure, settlement in downstream section, 10th section ovaled, 11th section has westward deflection
111	113	1	36	211						2	Looking East: 4/10' channelized sediment, infiltration at 1st joint, 2nd and 3rd joints separated, infiltration at 5th section, almost every joint is damaged or separated, 12th section deflects to South
111	527	1	18		338					4	Pipe is capped at structure 527
113	114	1	12		321					2	Looking North: Ovaling present in 2nd Section, 3rd section deflects south; Looking South: 2nd joint is separated, third section deflects to east, 5th section slopes down dramatically, potential collapse
113	115	1	12		380					3	Looking South: 2/10' sediment on west side, some separation at 1st joint, ovaling present in 5th and 6th sections, extreme ovaling in 7th section; Looking North: 4/10' sediment, Ovaling present in 2nd section
113	117	1	36	233						3	Looking East: 1' channelized sediment present, slight separation at 1st joint, some ovaling at 5th section, some bulging at 5th section on south side; Looking West: No field notes, no visible defects in limited video, sediment build-up, needs cleaning
114	139	1	12		300					3	Looking North: Pipe torn, ovaling present, slightly separated at 1st joint, 3rd section half-full of sediment; Looking South: tear in pipe, slight separation in 1st and 2nd joints, 4th section bulging on west side, 6th section deflects to west; pipe designed to flow south, flows north due to collected sediment
115	116	1	12		385					3	Looking South: 4/10' sediment, ovaling present in 1st and 4th sections; Looking North: 2-10' sediment, ovaling in 1st and 5th sections, large sinking depression in section 5.
117	118	1	18		401					3	Looking North: Some deflection to west, some sediment buildup, flow is in opposite direction of design; Looking South: Pipe almost half full of water, infiltration present in 5th and 6th sections of pipe, flow is in opposite direction of design
117	119	1	18		299					4	Severe shear (not sure why that note is here, it's not in the field notes); Looking South: Separation as pipe leaves structure, 3/10' channelized sedimentation, bows up after 3rd section, bellying present in 3rd section; Looking North: 3rd section deflects to west, 4th section deflects to east, ovaling at 5th and 6th sections
117	125	1	24	71						3	Looking East: 3/10' channelized sediment, separation at first joint; Looking West: 4/10' channelized sediment, separation at last joint.
119	120	1	18		285					3	Looking South: 4/10' channelized sediment present, 2nd section heaved, 3rd section deflects west, ovaling present in 4th section; Looking North: Separation at Structure
120	121	1	18	14						4	Looking East: Separation after leaving structure and at 1st section, bellied btwn. structures
120	122	1	12	46						4	Looking West: Separation after structure and 1st joint, 2nd section deflects south and up; Looking East: no delineator or flared section at pipe end, 2" of gravel in flow line at inlet, inlet partially blocked by gravel.
120	123	1	18		361					3	
123	124	1	18		401					2	Looking South: Pipe torn after structure, 3/10' gravel present, rock or cap present at 23.3'; Looking North: 1/10' sediment and gravel present in 1st section, 250' to rock obstruction
125	126	1	18		9					4	Looking West: no delineator or flared end section, small amount of rock inlet protection, 1" of gravel in flow line, inlet partially blocked by organic material
125	127	1	18		219					3	Looking North: Bellying after structure, roots penetrating seams; Looking South: 0.1' sediment, 0.2' sediment on sidewalls, 3rd section has ovaling
125	130	1	18		9					3	Looking South: 3/10' channelized sediment, root penetration at seams; Looking North: 2/10' channelized sediment
127	128	1	18		11					3	Looking North: 0.1' sediment, blockage at 217', 1/3 pipe full of sediment, gradually fills up more; Looking South: Too full of sediment to video
128	129	1	18		11					5	Looking East: Delineator with no flared end section at pipe end, inlet is free from obstructions and has rock inlet protection
130	131	1	18		302					3	Looking South: 1/10' channelized sediment, some deflection pretty far in; Looking North: bellying/sag present after structure, infiltration present at 1st joint
131	132	1	18		11					5	Looking East: 2/10' rocks, gravel and leaves present; Looking West: delineator at pipe end with no flared end section, rock inlet protection
131	133	1	18		300					3	Looking South: ovaling present, bulge present in 1st section, 4th section has bulging to the east and may be disconnected; Looking North: Bellying/sag present after structure, 2/10' water in pipe, bulge in lower part of pipe near structure 131
133	134	1	18		300					2	Looking South: deflection to west at end of 1st section, 2/10' sediment, raises up at 1st joint, significant deflection back to east; Looking North: no flow, should flow north, pipe dips and is blocked at 14.5'
134	135	1	18		11					3	Looking East: Sags after structure, piece of wood at structure entrance, significant rock debris at 135 inlet; Looking West: Delineator at pipe end with no flared section, significant amount of rocks at pipe entrance
134	136	1	18		199					3	Looking South: Deflects to east at 1.5', pipe half full of standing water, no flow; Looking North: some sediment and leaf debris present, ovaling after 1st section, deflection to east after 2nd section, deflects back to west shortly after, pipe bows down after deflecting down, 2/3 full of water
136	137	1	18		151					3	Looking South: Ovaling present at end of 1st section, infiltration present in ovaled section; Looking North: Bellying present after structure and in 2nd section, pipe rises at 1st joint, ovaling and slight deflection to east and back to west
137	138	1	18		10					4	Looking East: Pipe looks good; Looking West: Delineator with no flared end section at pipe end, mostly free of debris, little to no vegetation or rock inlet protection

Storm Drain Pipe Totals								
Storm Drain Pipe Type Totals (LF)	Pipe Size (Inch)	Pipe Type & Length (Feet)						Totals (LF)
		CPEP	CPEP, Perf (SUBDRAIN)	CMP	HDPE	DIP	CIPP	
	812	5,376	1,232	45	0	663	8,128	
	2	0	0	0	0	0	0	
	4	0	0	0	0	0	0	
	6	0	0	0	0	0	0	
	10	0	0	0	0	0	0	
	12	46	1,386	50	45	0	1,527	
	15	0	0	0	0	0	0	
	18	372	3,990	826	0	0	5,188	
	24	71	0	0	0	0	71	
	30	0	0	0	0	0	0	
	36	444	0	396	0	663	1,513	
	42	0	0	0	0	0	0	
	48	27	0	0	0	0	27	

Notes: 1. Pipe length totals encompass all of Storm Drain System 001; which includes pipes outside project limits.  
2. Pictures and Videos from the 2020 Structure and Pipe Condition Assessment can be found at:

<https://aro36587742.sharepoint.com/:f:/s/FileShare/Ep-xDJOqgDBLvsjRgPmSmUoBv7WAU5oMjn4ssiYyuSak0w7e=JfH8ZA>